37

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form



NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

Name of Property	ton:		
nistoric name Dr. Nat	han and Lula Cass House		
other names/site number The Mag	nolia House		
. Location		annaiseggs replaying	charen bha measta edhae
treet & number 502 N. Travis			not for publication
ity, town Cameron			vicinity
tate Texas code	TX county Milam	code 331	zip code 76520
Classification			150 - 157 - 147 - 158 - X
wnership of Property	Category of Property	Number of Resource	ces within Property
private	X building(s)	Contributing	Noncontributing
public-local	district	_ 1	2 buildings
public-State	site	0	0 sites
public-Federal	structure	0	0 structures
	object	0	1 objects
		1	3 Total
ame of related multiple property listing		Number of contribu	
ame of related multiple property listing	9.		iting resources previously
N/A	The state of the s	listed in the Nation	al Register N/A
National Register of Historic Places In my opinion, the property X meet Signature of certifying official State Historic Preservat	and meets the procedural and profe	ssional requirements set gister criteria. See cor	forth in 36 CFR Part 60.
State or Federal agency and bureau	and officery found in the con-	TCGT COMMITTER	
In my opinion, the property meet	s does not meet the National Re	gister criteria. See cor	ntinuation sheet.
Signature of commenting or other official			Date
State or Federal agency and bureau		Consideration of the second	
Natjønal Park Service Certifica	tion	2.15	Control of the Contro
hereby, certify that this property is: entered in the National Register. See continuation sheet. determined eligible for the National		ered in the ional Register	87ct.1991
Register. See continuation sheet. determined not eligible for the National Register.		my felicial in	
removed from the National Register other, (explain:)			-
	Signature of	the Keeper	Date of Action

6. Function or Use			
Historic Functions (enter categories from instructions)		actions (enter categories	
Domestic/single dwelling	Commer	cial/Trade/specia	alty store
To Table 1 to 1 t	sig abote	et to satelos	M legal
7. Description		11110 1 1	OF BUILDING
Architectural Classification (enter categories from instructions)	Materials (e	nter categories from inst	tructions)
	foundation	Brick	Liputago region baligo
Late Victorian/Queen Anne-Eastlake	walls	Wood/weatherboar	cd
	roof	Asbestos	Stepois to John
	other		The state of the
		N. A.A. S.	pault steles aren i

Describe present and historic physical appearance.

The 1895 Cass House is an ornate example of the Queen Anne and Eastlake styles in domestic architecture. The 2-story wood frame house is built on a modified rectangular plan with projecting wings and bays, and has an unusual configuration of overlapping gables at the roof. The focus of the design is a 2-story wraparound gallery with a highly embellished spindlework balustrade and frieze, and paneled walls. The house, its outbuildings and parking area occupy a full city block adjacent to the commercial district of Cameron, Milam County, in east central Texas.

The Cass House sits back from North Travis Avenue and West Sixth Street on a large, flat lot encompassing the southeast quadrant of its block. The house is shaded by several large oak trees and sits behind a cultivated lawn with planted beds around the house. The entire property is surrounded by a modern picket fence. Sidewalks, marked by 5-globe reproduction streetlight fixtures, lead to the south and east entries. A small bungalow, a gazebo and a garage sit on the southwest quadrant of the block, and the northern half is given over to parking.

The frame house is built on a pier-and-beam foundation skirted with brick. The focus of the house is on its southeast corner where the 2-story gallery wraps around, culminating at projecting gabled wings on the south and east facades. The L-plan gallery has a rounded corner and a pent roof between the first and second levels. Turned columns support the porch. The balustrade and frieze at both levels are fabricated of short turned pieces combined with jigsawn sections in a very ornate example of Eastlake trim. Entry is made to the porch (and house) at either end of the gallery, adjacent to the projecting wings. The pattern of the porch frieze changes above the entry bays, creating a curvilinear "curtain" of spindlework. A concrete ramp on the south and steps with a modern metal handrail on the east have replaced the original porch steps. The walls within the 2-story gallery are finished with paneled, end-grain pine in a treatment usually reserved for interiors. The double entry doors on the east have beveled glass windows and decorative carving and are set behind screen doors with jigsawn wooden frames that echo the forms of the doors. In addition to the entry doors, full-length walk-through sash windows are on both the first and second levels to provide access to the gallery.

The projecting gabled wings that bracket the gallery are very similar to each other. Both have a projecting bay at the first level with a bracketed pent

National Register of Historic Places Continuation Sheet

Section	number	7	Page	1
00001011			3-	

roof topped by a balustrade, creating a small balcony at the second level. The east bay is the most highly detailed, with paneled friezes and ornate moldings, while the south bay has more restrained detailing. The decorative brackets used in the bays and around the eaves of the house are fancy jigsawn and carved pieces set against a frieze of bullseye medallions. The bays are set with double-hung sash windows; the short windows in the south bay have replaced the original full-height windows. At the second level a pair of walk-through sash windows above each bay access the balconies. These windows, like the others throughout the house, have simple pedimented architraves. At the attic level the gable ends of the house are set with a small "Queen Anne" window of multipaned colored glass with a round window above it. These are surrounded by moldings and fanciful applied patterns, originally painted in contrasting colors.

The house is sided in weatherboard in those areas with less ornate finishes. Much of the distinctive detail of the house visually recedes into the present all-white paint scheme. The earliest known historic photograph shows a rich multi-colored scheme with a medium-tone background, dark trim at gable ends, bays, brackets and railings, a light color for the gallery frieze and porch details. In preparing the surfaces for repainting, the owners observed a range of yellow-cream tones with green accents that appeared to be the original colors. Asbestos tiles cover the original wood shingle roof. Two red brick chimneys pierce the roof; only one retains its corbeled top. The pent roofs of the porch and bays have dog-eared wood shingles painted red.

The secondary north and west facades, facing away from the street corner, have far more restrained finishes than the fronts of the house. The weatherboard siding is interrupted between the first and second floors by a 3-foot-wide course of vertical beaded board. Two of the walk-through first floor windows have been replaced by modern multi-light doors. A 1-story kitchen addition made on the west side in the 1920s has recently been finished with a bracketed pent roof and window surrounds to match the detailing of the main house.

The outside terrace on the west is surrounded by lattice screens and is set with modern iron street furniture and 5-globe light fixtures. To the west of the terrace is a long, 1-story gabled-roof frame garage built in the 1940s. A new gazebo sits to the northwest of the house, patterned after exterior details on the house. A small 1-story frame bungalow (used as a rent house) is on the southwest corner of the property, moved there in the 1940s. An original stable has been gone for some time. The parking lot on the north half of the block is minimally landscaped.

The interior finishes have largely survived. The entry hall is paneled with tight-grain curly pine, similar to the exterior porch walls, but in a

National Register of Historic Places Continuation Sheet

Section	number	7	Page	2
000000			5-	

pattern of offset panel. The spindle stair balusters have small bullseye medallions carved in their flat surfaces. Above the landing the balustrade is fabricated of spindles in a ship's wheel motif. A pine beaded board wainscot lines the stair well and upstairs hall. Windows, doors and transoms throughout the house are of pine with corner blocks hand-carved in motifs of flora and fauna, replacing the more typical bullseye medallions. (The unidentified woodcarver also built furniture for the house carved with similar motifs, but this has unfortunately been lost.) The two downstairs fireplace mantels have classical detailing and bevelled over-mirrors, applied foliated moldings and glazed tile. The two bedroom mantels are of simpler design with over-mirrors, bracketed shelves and glazed tile surrounds. All of the interior wood finishes have recently been stripped and revarnished, retaining their original appearance.

Alterations to the house are minimal. In the 1920s the room within the south bay was converted to a divided bath, resulting in the replacement of the full-length windows with shorter windows, as described above. A kitchen was added to the rear of the house, as mentioned. The library/office, parlor, dining room and bedrooms remain unchanged. The second floor bathroom is assumed to have been an early improvement; there is a portion of a stairway in that room that must have once led to the attic. An original dumbwaiter in the house has been removed. Overall the Cass House remains in a remarkable state of preservation.

8. Statement of Significance		hical References	estaelidig hojelê s
Certifying official has considered the significance of this prop	erty in state		
Applicable National Register Criteria A B XC			
Criteria Considerations (Exceptions)		□E □F □G N/A	
Areas of Significance (enter categories from instructions) Architecture		Period of Significance	Significant Dates N/A
		Cultural Affiliation	
Significant Person N/A		Architect/Builder Unknown	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The 1895 Cass House is among the best surviving examples of the embellished Queen Anne/Eastlake style in Texas. It illustrates a pattern of late 19th century domestic construction utilizing mass-marketed materials and house plans with elements of custom construction. It is nominated at the state level of significance under Criterion C, significant in the area of Architecture, for embodying the distinctive, highly-decorated aesthetic of the Victorian period, and exhibiting an exceptional level of craftsmanship.

The Cass House was built for Dr. Nathan Cass (1849-1906), a prominent Cameron physician, and his wife Lula Faulkner Cass (1859-1922). Dr. Cass operated his medical practice out of the house. He was an active member of the community, serving on the school board, the city council and as County Health Officer. The house stayed in Cass family hands until 1945 when it was sold to H.M. and Ora Lee Akers and the original furnishings were disposed of. In the late 1950s Wilford and Hattie Smith operated a popular restaurant out of the house called "The Magnolia House." Although the namesake magnolia tree no longer survives in the front yard, the current owners have kept the name for the house, which has been rehabilitated and is used for special functions.

Cameron was designated the county seat of Milam County in 1846, but it saw its greatest development in the late 19th century. Set in eastern central Texas, Milam County bridges the Eastern Cross Timbers and Blackland Prairie regions. Cotton grew well in the Blackland Prairie soil and it became the main cash crop in Milam County (as in much of Texas) after the Civil War. As the efficiency of cotton production and processing grew, along with the demand and price, it became the county's chief source of wealth. As the county seat, Cameron was the market center for the agricultural area and chiefly benefitted from this influx of cash.

The second major influence on Cameron's development in the late 19th century was the construction of the Gulf, Colorado & Santa Fe Railway (now the Atchison, Topeka & Santa Fe) through town in 1881. The railroad stimulated local growth by bringing people, trade and money in and taking cotton out, and

9. Major Bibliographical References	S. Statement of Stantificance
Drivery Plakely Alexander Tower Heres of the Nie	ng sim to empolitors and betablence and labello gravine?
Drury Blakely Alexander, <u>Texas Homes of the Nin</u> Press, Austin, 1966.	eteenth century, the university of Texas
History file on the house compiled by the curre	nt ormana from naviganal intermitare with
descendants of former owners, newspaper cli	nrings local arguesites and Miles
County Deed Records.	ppings, local gravesites and Milam
	1- Than #200A Care Harris C
Rex Z. Howard, Howard's Original Texas Guideboo	k, Item #288A, Cass HomeCameron,
p. 124, Lo-Ray Company, Grand Prairie, Texa	
Virginia and Lee McAlester, A Field Guide to Am	erican Houses, Alfred A. Knopf, New
York, 1988.	
Geoffrey Leavenworth and Richard Payne, Histori	c Galveston, Herring Press, Houston, 1985
John Poppeliers and S. Allen Chambers, What Sty	<u>le Is It?</u> , Preservation Press, Washington
D.C., 1984.	
Walter Prescott Webb, ed., The Handbook of Texa	s, Vol. 1 and 2.
and the second s	See continuation sheet
Previous documentation on file (NPS):	Signational Patable, April 1997
preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:
has been requested	State historic preservation office
previously listed in the National Register	Other State agency
previously determined eligible by the National Register	Federal agency
designated a National Historic Landmark	Local government
recorded by Historic American Buildings	University
Survey #	X Other
recorded by Historic American Engineering	Specify repository:
Record #	current owners' files
10. Geographical Data	
Acreage of property less than one	
A CONTRACTOR OF THE PARTY OF TH	
UTM References	
A 114 6 9 3 4 4 4 0 3 4 1 4 0 4 0	B
Zone Easting Northing	Zone Easting Northing
	See continuation sheet
Verbal Boundary Description	
One city block, bounded by West 6th Street, Tr	avis Avenue, Crockett Avenue, and West
5th Street, being all of Block 8, Freeman Addi	
	See continuation sheet
Boundary Justification	
The one square block described has been histor	ically associated with the Cass House
since construction began on the house in 1895.	
	See continuation sheet
11. Form Prepared By	
name/title Tory Laughlin Taylor, based on research	by Binnie Hoffman, consultant
organization Texas Historical Commission	date April, 1989; December, 1990
street & number P.O. Box 12276, Capitol Station	telephone 512/463-6094
city or town Austin	state Texas zin code 78711

National Register of Historic Places Continuation Sheet

Section number	8	Page	1
----------------	---	------	---

it reinforced Cameron's role as a regional market center. The railroad's influence on the physical development of the town was manifested in two ways: 1) it stimulated the economy resulting in an influx of people and a building boom; and 2) it transported building materials to Cameron that previously were unavailable locally.

The Cass House is a good example of the architectural result of this ready access to premanufactured building components. The ornate Eastlake balustrades, the small decorative windows, the eave brackets and fireplace surrounds of the Cass House are all distinctive features that were easily ordered out of catalogues from more distant markets now connected by the railroad. There is evidence that the fireplace surrounds and the eave brackets were catalogue stock. The milled wood components could have been produced at the local lumberyard, as increasingly small town yards obtained their own milling machinery brought in on the railroad, but Cameron has no comparable examples of the Eastlake trim used on the Cass House. The builder of the Cass House combined these prefabricated components with custom construction in a truly distinctive house. The unusual exterior paneling in the 2-story gallery was probably custom milled; although the origin of the paneling is not recorded, it may very well have been milled from East Texas pine not far from Cameron. other components of the house, such as the 1/1 windows, the lumber and siding, and most of the trim, were probably readily available as stock items; however, their availability too was due to rail transportation. While most of the interior moldings and trim are of a type commonly used in the 1890s, they were customized by a woodcarver who added images of plants and animals to the corner blocks of the doors and windows.

The Cass House is an exceptional Texas example of exuberant Victorian-era design in a largely intact condition. While the house is the product of a small agricultural center's prosperity in the 1890s, it compares favorably to the houses of Galveston built by wealthy merchants of that cosmopolitan port in the 1880s. Galveston has the greatest concentration of ornate Queen Anne/Eastlake houses in the state due to its prosperity in the late 19th century as the primary port of entry to Texas. Innumerable examples of the highly decorated galleries of the period are concentrated in the East End Historic District (N.R. 1975). Individual houses notable for their exuberance are the McDonald House (926 Winnie, 1889-90, continuation page 8-3) and the Sonnenthiel House (1826 Sealy Avenue, 1886-88, continuation page 8-4). The McDonald House uses a modified rectangular plan with a wraparound gallery similar to the Cass House and incorporates the ship's wheel motif seen inside the latter house on its exterior porch trim; however, its gallery is neither as large nor as ornatelydetailed as the Cass House's. The Sonnenthiel House, on the other hand, has a double gallery that achieves, through the complexity of components, an effect of laciness similar to the Cass House's; however, the form and motifs used in the house are quite different. Other notable examples in the state of the Eastlake

National Register of Historic Places Continuation Sheet

Section	number	8	Page	2
Occion	Hullibol		ugo	

double gallery are the Stephen & Mary Blount House in Nacogdoches (310 N. Mound, 1897, continuation page 8-5), the Fannie R. Jones House in Calvert (409 Gregg, c. 1880, continuation page 8-6), and the house at 515 East Main Street in Brenham (date unknown, continuation page 8-7), none of which incorporate the level of detail of the Cass House. The exterior paneling within the Cass House gallery is unique; no other examples of this treatment have been found in the state. Although the inspiration for this feature is unknown, it makes a statement for the intended use of the gallery as an extension of the interior of the house.

While the Cass House is distinguished by an extraordinary amount of milled wood decoration, the form of the house is not the apex of the Queen Anne style. Had the design been inspired by one of the profusion of Victorian-period patternbooks, the house would likely have incorporated a greater variety of projections, roof forms, porches and towers. The Cass House, however, has a more restrained plan and massing, and is unified by the 2-level wraparound gallery. Interestingly, it echoes quite closely the form of the John Bremond House in Austin (1886, N.R. 1970, continuation page 8-8), a Second Empire-style house of limestone construction with iron balustrade, columns and frieze on the wraparound gallery.

It is difficult to say where the builder of the Cass House got his inspiration. The form of the house is an evolved version of the much-used vernacular L-plan. The window treatments, bays and brackets reflect the established Italianate influence, and the house is detailed with some of the most ornate Eastlake embellishment then available. The Cass House may be considered the distinctive product of the confluence of Cameron's late 19th-century prosperity, a client with wealth and eclectic taste, a creative local builder working with forms familiar to him, and the availability of a variety of premanufactured building components in the ornate Eastlake style then in vogue.

National Register of Historic Places Continuation Sheet

Section number ____8 Page __3__



McDonald House



McDONALD HOUSE 1889 or 1890 926 Winnie

National Register of Historic Places Continuation Sheet

Section number ____8 Page ___4



172. The Sonnenthiel House, Galveston


National Register of Historic Places Continuation Sheet

Section number 8 Page 5



National Register of Historic Places Continuation Sheet

Section number 8 Page 6



Fannie R. Jones House, 409 Gregg Calvert, TX c. 1880

National Register of Historic Places Continuation Sheet


Section number 8 Page 7



180. The House at 515 Main Street, Brenham

National Register of Historic Places Continuation Sheet

Section number ___8 Page __8



185. The John Bremond House, Austin

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NO	MINATION			
PROPERTY Cass, Dr. NAME:	Nathan and Lu	la, House		
MULTIPLE NAME:				1
STATE & COUNTY: TEXA	S, Milam			
DATE RECEIVED: DATE OF 16TH DAY: DATE OF WEEKLY LIST:				
REFERENCE NUMBER: 91	000037			
NOMINATOR: STATE				
REASONS FOR REVIEW:				
APPEAL: N DATA PROB OTHER: N PDIL: REQUEST: N SAMPLE:	N PERIO	D: N PF	ROGRAM UNAPPROV	
COMMENT WAIVER: N				
RETUR	NREJEC	T 874 159	DATENational	In the
ABSTRACT/SUMMARY COMM	ENTS:			

DOCUMENTATION see attached comments Y/N see attached SLR Y/N

CLASSIFICATI	ON
count	resource type
all all all i	
STATE/FEDERA	AL AGENCY CERTIFICATION
FUNCTION	
historic	current
DESCRIPTION	
	cural classification
materials descripti	
descripti	ve text
SIGNIFICANCE	
Period	Areas of SignificanceCheck and justify below
Specific dat	es Builder/Architect
Statement of	Significance (in one paragraph)
applicabljustificarelatingcontextrelations	Le criteria ation of areas checked significance to the resource ship of integrity to significance ation of exception
BIBLIOGRAPHY	
GEOGRAPHICAL	DATA
acreage UTMs	verbal boundary descriptionboundary justification
ACCOMPANYING	DOCUMENTATION/PRESENTATION
	B DOCUMENTATION/PRESENTATION ApsUSGS mapsphotographspresentation
	psUSGS mapsphotographspresentation
sketch ma	psUSGS mapsphotographspresentation



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOS NOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING NORTHWEST

PHOTO 1 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

PHOTOGRAPHER UNKNOWN

BEFORE 1906

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING NORTHWEST

PHOTO 2 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO. TEXAS

PHOTOGRAPHER UNKNOWN

CA. 1955

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING NORTHWEST

PHOTO 3 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING WEST-NORTHWEST

PHOTO 4 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING SOUTH

PHOTO 5 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING SOUTHWEST

PHOTO 6 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING NORTH-NORTHWEST

PHOTO 7 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING: FIRST FLOOR GALLERY DETAIL

PHOTO 8 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

CAMERA FACING EAST (GARAGE IN RELATION TO HOUSE)

PHOTO 9 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

1940'S RENT HOUSE IN RELATION TO CASS HOUSE

CAMERA FACING SOUTHEAST

PHOTO 10 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAMS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

PARKING LOT IN RELATION TO CASS HOUSE

CAMERA FACING SOUTH-SOUTHEAST

PHOTO 11 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS
ENTRY HALL

CAMERA FACING WEST

PHOTO 12 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

FIRST FLOOR ENTRY HALL CORNER BLOCK DETAIL

PHOTO 13 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAMS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAMS, CAMERON, TEXAS

SECOND FLOOR SOUTHWEST BEDROOM CORNER BLOCK DETAIL

PHOTO 14 of 19



DR. NATHAN & LULA CASS HOUSE

SOZ N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSHOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

LIBRARY / DR. CASS' OFFICE MANTEL DETAIL

PHOTO 15 of 19



DR. NATHAN & LULA CASS HOUSE

50Z N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 50Z N. TRAVIS, CAMERON, TEXAS

SOUTHEAST SECOND FLOOR BEDROOM MANTEL DETAIL

PHOTO 16 of 19



DR. NATHAN & LULA CASS HOLSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

LIOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

NORTHEAST SECOND FLOOR BEDROOM (NOW SITTING ROOM) - MANTEL DETAIL

PHOTO 17 of 19



DR. NATHAN & LULA CASS HOUSE

FOR N. TRAMS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWY

MAY 1989

NEGATIVE AT 502 N. TRAMS, CAMERON, TEXAS

DINING ROOM

CAMERA FACING SOUTH

PHOTO 18 of 19



DR. NATHAN & LULA CASS HOUSE

502 N. TRAVIS

CAMERON, MILAM CO., TEXAS

JOHN SOSNOWT

MAY 1989

NEGATIVE AT 502 N. TRAVIS, CAMERON, TEXAS

DINING ROOM

CAMERA FACING SOUTH

PHOTO 19 of 19

